



Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7 RELAXATION OF SiGe ON SiO<sub>2</sub> AFTER WAFER SPLITTING AND ANNEAL




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




Fig. 14

